



Contractor's Qualifying Statement

Submitted by: Hal Bolter, *President*

Our Name: Regions Facility Services, Inc. (RFS®)

Addresses:

2314 Circuit Way, Brooksville, FL 34604 (Headquarters)

524 W. Belvedere St., Lakeland, FL 33803

2401 Delgado Dr., Tallahassee, FL 32304

104 Deana St. Ste. A, Robinson, TX 76706

3501 MacCorkle Ave. SE, Charleston, WV 25304

Date of Incorporation: September 1, 2003

State of Incorporation: Florida; offices in Florida, Texas, and West Virginia

Classifications of Directed and Self-Performed Work:

Restaurant, Senior Living, Hospitality, Commercial Build-out, Remodel, Roll-out, and Renovations: Exterior, Interior, Commercial Kitchen, Guest Areas, Bar, Equipment.

Major upgrades including Walk-in-Cooler/Freezer, Dish Rings, Cook Lines, Restrooms, Bars, Patios, Landscape, Paint, Carpet, Tile, Walls, etc.

Ever failed to complete an award? No

Within the last five years, has any officer or partner ever failed to complete a construction contract awarded to them (with another organization or RFS®)? No

Officers

Ronald T. Wilhite
CEO

Hal Bolter
President

Ronald T. Wilhite
Secretary

Kristen Bolter
Treasurer

Licensed GC's

Ronald T. Wilhite
CBC045632-FL

John Evans
CBC1253841-FL

Daniel Farley
WV057432-WV

Additional state, regional, and local licenses available upon request.

Incorporation

Date

September 1, 2003

Original State

Florida

Years in Business

17



Recent Projects

Hard Rock Café, Bayside, Miami, FL: \$1,209,080.00

Full remodel of Kitchen, Bar, Dining Room, Rock Shop, and Guest Restrooms; all work performed at night for 12+ weeks, managed multiple trade subcontractors, and kept location fully operational throughout.

*Ed Bordelon, VP of Construction & Facilities, Hard Rock Cafe:
ed.bordelon@hardrock.com*

Tavistock Restaurant Collection, ATLAS, Atlanta, GA: \$337,140.00

Restaurant remodel to include Dish Ring, Bakery, Tile & Grout, Kitchen, Electrical, Ceilings (Tile, Grid, & Stucco), Glass Canopy, Plumbing, and Core Drilling; all work performed at night for 9+ weeks, managed multiple trade subcontractors, and kept location fully operational throughout.

*Eric Rainville, Director of Facilities, Tavistock Restaurant Collection:
ericrainville@tavistockrestaurants.com*

Darden Restaurants, Eddie V's, San Antonio, TX: \$246,904.00

Brand conversion with upgrades to Bar, Lighting, Flooring, and Doors; managed several suppliers, trade subcontractors, and critical path materials.

*Doug Estes, Director of Specialty Restaurant Group, Darden Restaurants:
destes@darden.com*

Texas Roadhouse, Brooksville, FL: \$248,288.00

Refresh/Remodel to include Exterior Skin & Tin replacement, To Go Upgrades, Interior Upgrades, Tabletop Installation; work completed both at night and during the day, kept location fully operational throughout.

*James Gault, Director of Facilities Maintenance, Texas Roadhouse:
james.gault@texasroadhouse.com*

Bank Reference

Capitol City Bank

14302 Spring Hill Drive
Spring Hill, FL 34609
Tyler Stapleton, President
stapleton.tyler@ccbg.com
352.293.5595

Trade References

Daltile

800.449.3591

Dumpster World

807.609.9737

Sherwin Williams Co.

800.474.3794

Suncoast Plumbing

352.628.6608

Titan Electric

407.667.4080

Bonding Company & Agent

Marsh & McLennan/

Bouchard Insurance

1 N. Dale Mabry Hwy,
Ste 450, Tampa, FL 33609

Mark Pichowski

CPA, Surety Specialist

Mark.Pichowski@

MarshMMA.com

727.373.2710

2314 Circuit Way, Brooksville FL 34604

phone: 844.RFS.RENO (844.737.7366)

email: info@RFSrenovates.com

web: RFSrenovates.com